

# The Design – in Faults as a Causes of the High Performance Machines Failures

Srđan M. Bošnjak<sup>1,\*</sup> - Zoran D. Petković<sup>1</sup> - Milojević Z. Goran<sup>1</sup> - Vaso M. Mihajlović<sup>1</sup>

<sup>1</sup>University in Belgrade - Faculty of Mechanical Engineering

*High capacities and key roles in the technological processes cause the extremely high financial losses in the case of high performance machines failures. This paper presents case studies of bucket wheel excavators, stackers and bucket chain reclaimers failures caused by design – in faults. Besides that, paper gives a redesign solutions which are developed by University of Belgrade – Faculty of Mechanical Engineering.*

**Keywords:** High performance machines, design-in faults, redesign

## 0 INTRODUCTION

The high performance machines (HPM), such as bucket wheel excavators (BWE), Fig. 1, bucket chain excavators (BCE), Fig. 2, and bucket chain reclaimers (BCR), Fig. 3, are the backbones of the open pit coal mining and thermal plant mechanization systems. Their exploitation in harsh working conditions provides fertile ground for the occurrence of various types of failures [1-10]. In reference [11] it was stated that there are four main reasons for the collapse of high-capacity earthmoving and lifting/conveying machines:

- design faults, so-called ‘designing-in’ defects;
- manufacture faults causing the so-called ‘manufacturing-in’ defects;
- exploitation faults (by analogy, these causes can be named ‘operating-in’ defects);
- extreme environmental impacts – unusual occurrences (extreme storm, earthquake, fire); by analogy, these causes can be named ‘environment-in’ defects.

Common denominators to all failure of machines, particularly the HPM, are very high financial losses and serious risks to the worker’s safety and life [12]. When it comes to BWE, BCE and BCR, financial losses caused by production delays due to the principal machine failure in a surface mining system, i.e. coal storage and shipment, often significantly exceed the financial losses caused by direct material damage. The size of the negative economic effects caused by failures is remarkably revealed in the fact that the total cost of failure in USA and Europe is of order of 4% of GNP [13].

Researches presented in this paper are focused on HPM vital parts damages caused by design – in faults and their redesign.



Fig. 1. Bucket wheel excavator SRs 1201



Fig. 2. Bucket chain excavator ERs 1000



Fig. 3. Bucket chain reclaimer Metalna 300

\*Corr. Author's Address: Faculty of Mechanical Engineering, Kraljice Marije 16, Belgrade, Serbia, sbosnjak@mas.bg.ac.rs

## 1 FAILURE AND REDESIGN OF THE BWE BUCKET AND BUCKET WHEEL

BWE SRs 1201.24/4, Fig. 4, was put in exploitation in 2003. During exploitation some drawbacks in buckets' leaning zones were observed, as follows:

- Damages of the pins and bushing of the bucket eyes, Fig. 4;
- Damages and plastic deformations of the bucket wheel front supporting eyes, Fig. 5;
- Plastic deformations of the bucket wheel rear supporting eyes, Fig. 6;
- Bucket "opening" in the rear support zone, Fig. 6.

In order to eliminate the presented drawbacks, it was necessary to redesign the bucket supporting zones, Figs. 7-10.




Fig. 4. Pushed out bushing of the front bucket eye




Fig. 5. Plastic deformations of the front bucket wheel eye




Fig. 6. Plastic deformations of the rear support eye and bucket "opening" in the rear support zone




Fig. 7. 3D model of the original bucket: zones of redesign




Fig. 8. Redesigned bucket



Fig. 9. Welding of the redesigned front support eye



Fig. 10. Welding of the redesigned rear support eye

Obviously, redesign of the bucket cause the change of its weight. In considered case, reconstruction of one bucket with its supports on bucket wheel increase weight for  $\Delta G_B = 43.2$  daN. Having in mind that total number of bucket is  $n_B = 14$ , total weight increase can be calculated as

$$\Delta G = n_B \Delta G_B = 14 \times 43.2 = 604.8 \text{ daN} \quad (1)$$

Fig. 11.

Center of gravity location, Fig. 11, is calculated by using Varignon's theorem

$$\begin{aligned} x_{GN}^* &= \frac{G_N x_{GN} + \Delta G_{PU} x_{\Delta G_{PU}} + \Delta G x_{\Delta G}}{G_N + \Delta G_{PU} + \Delta G} = \\ &= \frac{7705.3 \times 0.011 + 450 \times 7.95 - 6.1 \times 33.083}{7705.3 + 450 + 6.1} = \quad (2) \\ &= 0.424 \text{ m} \end{aligned}$$

So, the increase of the redesigned buckets' weight cause the change of the center of gravity location. For horizontal position of the bucket wheel boom shifting of the center of gravity is

$$x_{GN} - x_{GN}^* = 0.449 - 0.424 = 0.025 \text{ m} \quad (1)$$

which is allowable.




Fig. 11. Scheme for calculation of the center of gravity location after buckets redesign (superstructure weight  $G_S = 7705.3$  kN,  $x_{GN} = 0.449$  m; part of conveyor weight  $\Delta G_C = 450$  kN,  $x_{\Delta G_C} = 7.95$  m; total weight increase  $\Delta G = 6.1$  kN,  $x_{\Delta G} = -33.083$  m)

Buckets and bucket wheel were redesigned in october 2009. Validation of the applied solution is done by expert's evaluation of the machine behaviour during exploitation as well as by visual inspection of the critical zones.

## 2 FAILURE AND REDESIGN OF THE BCE STRUCTURE

BCE ERs 1000, Fig. 2, is in use in open pit mine "Kolubara". During perennial exploitation cracks were observed on the column heads of supporting truss of the counterweight boom (CWB) Fig. 12. These cracks have been weld repaired, but after some time they appear again, being longer and longer.

The cracks propagation could lead to catastrophic consequences – collapse of the machine, such as described in [1,6]. The goals of the study presented in the paper were to:

- Diagnose the cause of cracks occurrence;
- Define the reconstruction design of the truss columns, Fig. 13;
- Verify the reconstructed structure by numerical-experimental analysis, Figs. 14 and 15.




Fig. 12. Cracks on the CWB supporting truss columns




Fig. 13. 3D models of the original (a) and redesigned (b) column head



Fig. 14. Set up and connection of strain gauges

Based on the results of a comparative numerical analysis of the original and redesigned structure of the column head, the authors conceived a reconstruction solution that meets the following requirements:

- a significantly lower stress state ( $\approx 3$  times) in critical zones, where peaks do not exceed allowable values;
- a very short time for manufacturing of the redesigned columns' parts;
- the possibility of performing reconstruction in field conditions, without dismantling the BCE superstructure components.

Experimental analysis of the stress state of the redesigned column heads was carried out in June 2010, during BCE testing immediately after the finished reconstruction.

Visual inspection performed in April 2011 proved that there are no defects in the structure of the redesigned column heads. The validity of the presented reconstruction, besides experimental investigations, unquestionably confirms failureless exploitation, where BWE excavated more than  $1.4 \times 10^6$  t of coal after the reconstruction.

### 3 FAILURE AND REDESIGN OF THE BCR STRUCTURE

Design-in faults led to buckling of the rigid portal bracing, Fig. 15, and collapse of the machine structure.



Fig. 15. Detail of rigid leg

After the reconstruction of the truss substructure in critical zone, stress levels became considerably lower. Besides that, increasing of bracing and horizontal truss stiffness, Figs. 16 and 17, as well as increasing of torsional stiffness of portal legs, Fig. 18, led to displacements decreasing [14-17].




Fig. 16. Redesigned bracing truss

Exploitation experience after the structure reconstruction confirmed the validity of applied redesign solutions as well as calculation procedure.



Fig. 16. Redesigned bracing truss




Fig. 17. Redesigned horizontal truss




Fig. 18. Closing of the portal cross-section

### 4 CONCLUSION

The fundamental problems of any machine subsystem's redesign, therefore the BWE, BCE and BCR substructures as well, are caused by the

restriction ensuing from installation conditions and functionality. Special difficulties result from the relative complexity of the considered structures, as well as the nature of external operational loads. The mentioned loads are of an outstandingly dynamic and stochastic nature, so that calculated loads are assumptions, in the full sense of the word. And exactly because of that, comparative stress analysis presents an indispensable and inevitable part of the redesign process.

Finally, the validity of the presented reconstructions, besides expert evaluations and experimental investigations, unquestionably confirms failureless exploitation.

### Acknowledgement

This work is a contribution to the Ministry of Science and Technological Development of Serbia funded project TR 35006.

### 4 REFERENCES

- [1] Rusiński E, Czmochowski J, Iluk A, Kowalczyk M. An analysis of the causes of a BWE counterweight boom support fracture. *Eng Fail Anal* 2010;17:179–91.
- [2] Rusiński E, Czmochowski J, Moczko P. Half-shaft undercarriage systems – designing and operating problems. *JAMME* 2009;33:62–9.
- [3] Rusiński E, Czmochowski J, Smolnicki T. Failure reasons investigations of dumping conveyor breakdown. *JAMME* 2007;23: 75–8.
- [4] Rusiński E, Harnatkiewicz P, Kowalczyk M, Moczko P. Examination of the causes of a bucket wheel fracture in a bucket wheel excavator. *Eng Fail Anal* 2010;17:1300–12.
- [5] Savković M, Gašić M, Arsić M, Petrović R. Analysis of the axle fracture of the bucket wheel excavator. *Eng Fail Anal* 2011;18:433–41.
- [6] Bošnjak S, Zrnić N, Simonović A, Momčilović D. Failure analysis of the end eye connection of the bucket wheel excavator portal tie-rod support. *Eng Fail Anal* 2009;16:740–50.
- [7] Bošnjak S, Petković Z, Zrnić N, Simić G., Simonović A. Cracks, repair and reconstruction of bucket wheel excavator slewing platform. *Eng Fail Anal* 2009;16:1631–42.
- [8] Bošnjak S, Petković Z, Zrnić N, Pantelić M, Obradović A. Failure analysis and redesign of the bucket wheel excavator two-wheel bogie. *Eng Fail Anal* 2010;17:473–485.
- [9] Bošnjak S, Pantelić M, Zrnić N, Gnjatović N, Đorđević M. Failure analysis and reconstruction design of the slewing platform mantle of the bucket wheel excavator O&K SchRs 630. *Eng Fail Anal* 2011;18:658–69.
- [10] Arsić M, Bošnjak S, Zrnić N, Sedmak S, Gnjatović N. Bucket wheel failure caused by residual stresses in welded joints. *Eng Fail Anal* 2011;18:700–12.
- [11] Bošnjak S, Arsić M, Zrnić N, Rakin M, Pantelić M. Bucket wheel excavator: integrity assessment of the bucket wheel boom tie – rod welded joint. *Eng Fail Anal* 2011;18:212–222.
- [12] Wintle JB, Pargeter RJ. Technical failure investigation of welded structures (or how to get the most out of failures). *Eng Fail Anal* 2005;12:1027–37.
- [13] de Castro PMST, Fernandes AA. Methodologies for failure analysis: a critical survey. *Mater Design* 2005;25:117–23.
- [14] Bošnjak S, Gašić V, Petković Z. Determination of resistances to coal reclaiming at bridge - type stacker – reclaimer with bucket chain booms. *FME Transactions* 2005; 33:79 – 88.
- [15] Bošnjak S, Petković Z, Gašić V, Zrnić N. Pretovarni mostovi sa elevatorima – Deo I: Identifikacija opterećenja, proračun strukture i zakošavanje. *Tehnika – Mašinstvo* 2006; 55:1–6. (in Serbian)
- [16] Bošnjak S, Petković Z, Gašić V, Zrnić N. Pretovarni mostovi sa elevatorima – Deo II: Konstrukciono rešenje, tehnologija i proračun rekonstruisane strukture. *Tehnika – Mašinstvo* 2007;56:7–13. (in Serbian)
- [17] Bošnjak S. Some of the problems on dynamics and strength of the high - performance machines. *iipp* 2010;8:1–12. (in Serbian)